

# HWL 6100 28-Key Keyboard Map

## Booting Procedures

Boot Type	Procedure
Warm Boot	Press reset button left of power button.
Cold Boot	Press power button + reset button.

## Local Terminal Functions

Local Function	Key Sequence
Program Information	NA
Diagnostics	NA
Keyclicks On/Off	NA
Quiet Mode On/Off	NA
Terminal Configuration	NA
Host Profiles	NA
Message Recall	NA
Free Cursor Mode	NA
Close Session	NA
Previous Session	NA
Next Session	NA
Caps Lock	<ALPHA>*
View Mode On/Off	NA
Scroll Left	NA
Scroll Right	NA
Scroll Up	NA
Scroll Down	NA

## Industrial Browser Keys

Web Key	Key Sequence
Home	NA
Back	NA
Forward	NA
Stop	NA
Refresh	NA

\*Must press the ALPHA key to type numbers, small, and upper case letters.

# HWL 6100 28-Key Keyboard Map

## 5250 Emulation Keys

5250 Key	Key Sequence
Attention	NA
Backspace	<BKSP>
Back Tab	NA
Clear	NA
Delete	NA
Dup	NA
Enter	<ENT>
Erase Input	NA
Field Exit	NA
Field Minus	NA
Help	NA
Home	NA
Insert	NA
Print	NA
Reset	<ESC>
Roll Up	NA
Roll Down	NA
System Request	NA
Tab	<FUNC><7>
Left Arrow	<Left><Arrow>
Right Arrow	<Right><Arrow>
Up Arrow	<Up><Arrow>
Down Arrow	<Down><Arrow>

5250 Key	Key Sequence
F1	F1
F2	F2
F3	F3
F4	F4
F5	<FUNC> <1>
F6	<FUNC> <2>
F7	<FUNC> <3>
F8	NA
F9	NA
F10	NA
F11	NA
F12	NA
F13	NA
F14	NA
F15	NA
F16	NA
F17	NA
F18	NA
F19	NA
F20	NA
F21	NA
F22	NA
F23	NA
F24	NA

# HWL 6100 28-Key Keyboard Map

## 3270 Emulation Keys

3270 Key	Key Sequence
Attention	NA
Backspace	<BKSP>
Back Tab	NA
Clear	<ESC>
Clear EOF	NA
Delete	NA
Dup	NA
Enter	<ENT>
Erase Input	NA
Field Mark	NA
Home	NA
Insert	NA
New Line	NA
Reset	NA
System Request	NA
Tab	<FUNC><7>
Left Arrow	<Left><Arrow>
Right Arrow	<Right><Arrow>
Up Arrow	<Up><Arrow>
Down Arrow	<Down><Arrow>
PA1	NA
PA2	NA
PA3	NA

3270 Key	Key Sequence
F1	F1
F2	F2
F3	F3
F4	F4
F5	<FUNC> <1>
F6	<FUNC> <2>
F7	<FUNC> <3>
F8	NA
F9	NA
F10	NA
F11	NA
F12	NA
F13	NA
F14	NA
F15	NA
F16	NA
F17	NA
F18	NA
F19	NA
F20	NA
F21	NA
F22	NA
F23	NA
F24	NA

# HWL 6100 28-Key Keyboard Map

## VT-100 Emulation Keys

VT-100 Key	Key Sequence
Return	NA
Backspace	<BKSP>
Tab	<FUNC><7>
Up Arrow	<Up><Arrow>
Left Arrow	<Left><Arrow>
ESC	<ESC>
BS	NA
LF	NA
Hard Terminal Reset	NA

VT-100 Key	Key Sequence
Enter	<ENT>
Backspace(Delete)	NA
Backtab	NA
Down Arrow	<Down><Arrow>
Right Arrow	<Right><Arrow>
PF1	NA
PF2	NA
PF3	NA
PF4	NA

## VT-220 Emulation Keys

VT-220 Key	Key Sequence
Return	NA
Backspace	<BKSP>
Tab	<FUNC><7>
Up Arrow	<Up><Arrow>
Left Arrow	<Left><Arrow>
Hard Terminal Reset	NA
Find	NA
Insert Here	NA
Prev Screen	NA
PF1	NA
PF2	NA
PF3	NA
PF4	NA
BREAK <sup>1</sup>	NA
F6	<FUNC> <2>
F7	<FUNC> <3>
F8	NA
F9	NA
F10	NA

VT-220 Key	Key Sequence
Enter	<ENT>
Backspace(Delete)	NA
Backtab	NA
Down Arrow	<Down><Arrow>
Right Arrow	<Right><Arrow>
Soft Terminal Reset	NA
Select	NA
Remove	NA
Next Screen	NA
F11	NA
F12	NA
F13	NA
F14	NA
F15/Help	NA
F16/Do	NA
F17	NA
F18	NA
F19	NA
F20	NA

# HWL 6100 28-Key Keyboard Map

## HP Emulation Keys

HP Key	Key Sequence
Return	NA
Backspace	<BKSP>
Tab	<FUNC><7>
Up Arrow	<Up><Arrow>
Left Arrow	<Left><Arrow>
Insert Line	NA
Insert Char	NA
Hard Terminal Reset	NA
Prev	NA
Clear Line	NA
Insert Char with wrap	NA
Scroll Down	NA
F1	F1
F2	F2
F3	F3
F4	F4
User Key Menu	NA

HP Key	Key Sequence
Enter	<ENT>
Backspace(Delete)	NA
Backtab	NA
Down Arrow	<Down><Arrow>
Right Arrow	<Right><Arrow>
Delete Line	NA
Delete Char	NA
Soft Terminal Reset	NA
Next	NA
Clear Display	NA
Delete Char with wrap	NA
Scroll Up	NA
F5	<FUNC> <1>
F6	<FUNC> <2>
F7	<FUNC> <3>
F8	NA
System Modes Menu	NA

# HWL 6100 28-Key Keyboard Map

5250/3270/VT/HP Character Map

Char	Key Sequence
Space	<SP>
!	<CTRL><<1>
“	NA
#	<CTRL><<3>
\$	<CTRL><<4>
%	<CTRL><<5>
&	<CTRL><<7>
'	NA
(	<CTRL><<8>
)	<CTRL><<9>
*	<CTRL><<0>
+	<CTRL><<SP>
,	NA
-	<CTRL><<. >
.	<. >
/	NA
0	<0>*
1	<1>
2	<2>
3	<3>
4	<4>
5	<5>
6	<6>
7	<7>
8	<8>
9	<9>
:	NA
;	NA
<	NA
=	NA
>	NA
?	NA
@	<CTRL><<2>

Char	Key Sequence
A	<A>*
B	<B>
C	<C>
D	<D>
E	<E>
F	<F>
G	<G>
H	<H>
I	<I>
J	<J>
K	<K>
L	<L>
M	<M>
N	<N>
O	<O>
P	<P>
Q	<Q>
R	<R>
S	<S>
T	<T>
U	<U>
V	<V>
W	<W>
X	<X>
Y	<Y>
Z	<Z>
[	NA
\	NA
]	NA
^	<CTRL><<6>
_	NA
`	NA

Char	Key Sequence
a	<A>*
b	<B>
c	<C>
d	<D>
e	<E>
f	<F>
g	<G>
h	<H>
i	<I>
j	<J>
k	<K>
l	<L>
m	<M>
n	<N>
o	<O>
p	<P>
q	<Q>
r	<R>
s	<S>
t	<T>
u	<U>
v	<V>
w	<W>
x	<X>
y	<Y>
z	<Z>
{	NA
	NA
}	NA
~	NA

\*Must press the ALPHA key to type numbers, small, and upper case letters.

# HWL 6100 28-Key Keyboard Map

## 5250/3270/VT/HP Character Map

Char	Key Sequence
^@	NA
^A	NA
^B	NA
^C	NA
^D	NA
^E	NA
^F	NA
^G	NA
^H	NA
^I	NA
^J	NA
^K	NA
^L	NA
^M	NA
^N	NA
^O	NA
^P	NA
^Q	NA
^R	NA
^S	NA
^T	NA
^U	NA
^V	NA
^W	NA
^X	NA
^Y	NA
^Z	NA
ESC	NA
^\	NA
^]	NA
^^	NA
^_	NA