

Honeywell 6500 52-Key Keyboard Map

Booting Procedures

Boot Type	Procedure
Warm Boot	Press the reset button by the scan button
Cold Boot	Hold down blue + z and then press the reset button

Local Terminal Functions

Local Function	Key Sequence
Program Information	NA
Diagnostics	NA
Keyclicks On/Off	NA
Quiet Mode On/Off	NA
Terminal Configuration	NA
Host Profiles	NA
Message Recall	NA
Free Cursor Mode	NA
Close Session	NA
Previous Session	<CTRL><Left>
Next Session	<CTRL><Right>
Caps Lock	NA
View Mode On/Off	NA
Scroll Left	NA
Scroll Right	NA
Scroll Up	NA
Scroll Down	NA

Industrial Browser Keys

Web Key	Key Sequence
Home	<CTRL><H>
Back	<CTRL>
Forward	<CTRL><F>
Stop	<CTRL><S>
Refresh	<CTRL><R>

Honeywell 6500 52-Key Keyboard Map

5250 Emulation Keys

5250 Key	Key Sequence
Attention	<CTRL><A>
Backspace	<BKSP>
Back Tab	<SFT><TAB>
Clear	<CTRL><C>
Delete	NA
Dup	<CTRL><4>
Enter	<CTRL><ENT>
Erase Input	<CTRL><E>
Field Exit	<ENT>
Field Minus	NA
Help	<CTRL><G>
Home	NA
Insert	NA
Print	<CTRL><P>
Reset	<ESC>
Roll Up	NA
Roll Down	NA
System Request	<CTRL><S>
Tab	<TAB>
Left Arrow	<Left Arrow>
Right Arrow	<Right Arrow>
Up Arrow	<Up Arrow>
Down Arrow	<Down Arrow>

5250 Key	Key Sequence
F1	<Red><1>
F2	<Red><2>
F3	<Red><3>
F4	<Red><4>
F5	<Red><5>
F6	<Red><6>
F7	<Red><7>
F8	<Red><8>
F9	<Red><9>
F10	<Red><0>
F11	NA
F12	NA
F13	NA
F14	NA
F15	NA
F16	NA
F17	NA
F18	NA
F19	NA
F20	NA
F21	NA
F22	NA
F23	NA
F24	NA

Honeywell 6500 52-Key Keyboard Map

3270 Emulation Keys

3270 Key	Key Sequence
Attention	<CTRL><A>
Backspace	<BKSP>
Back Tab	<SFT><TAB>
Clear	<ESC>
Clear EOF	<CTRL><O>
Delete	NA
Dup	<CTRL><4>
Enter	<ENT>
Erase Input	<CTRL><E>
Field Mark	<CTRL><F>
Home	NA
Insert	NA
New Line	NA
Reset	<CTRL><R>
System Request	<CTRL><S>
Tab	<TAB>
Left Arrow	<Left Arrow>
Right Arrow	<Right Arrow>
Up Arrow	<Up Arrow>
Down Arrow	<Down Arrow>
PA1	<CTRL><1>
PA2	<CTRL><2>
PA3	<CTRL><3>

3270 Key	Key Sequence
F1	<Red><1>
F2	<Red><2>
F3	<Red><3>
F4	<Red><4>
F5	<Red><5>
F6	<Red><6>
F7	<Red><7>
F8	<Red><8>
F9	<Red><9>
F10	<Red><0>
F11	NA
F12	NA
F13	NA
F14	NA
F15	NA
F16	NA
F17	NA
F18	NA
F19	NA
F20	NA
F21	NA
F22	NA
F23	NA
F24	NA

Honeywell 6500 52-Key Keyboard Map

VT-100 Emulation Keys

VT-100 Key	Key Sequence
Return	NA
Backspace	<BKSP>
Tab	<TAB>
Up Arrow	<Up Arrow>
Left Arrow	<Left Arrow>
ESC	<ESC>
BS	NA
LF	<CTRL><J>
Hard Terminal Reset	NA

VT-100 Key	Key Sequence
Enter	<ENT>
Backspace(Delete)	<BKSP>
Backtab	<SFT><TAB>
Down Arrow	<Down Arrow>
Right Arrow	<Right Arrow>
PF1	NA
PF2	NA
PF3	NA
PF4	NA

VT-220 Emulation Keys

VT-220 Key	Key Sequence
Return	NA
Backspace	<BKSP>
Tab	<TAB>
Up Arrow	<Up Arrow>
Left Arrow	<Left Arrow>
Hard Terminal Reset	NA
Find	<CTRL><5>
Insert Here	NA
Prev Screen	NA
PF1	NA
PF2	NA
PF3	NA
PF4	NA
BREAK ¹	NA
F6	<Red><6>
F7	<Red><7>
F8	<Red><8>
F9	<Red><9>
F10	<Red><0>

VT-220 Key	Key Sequence
Enter	<ENT>
Backspace(Delete)	<BKSP>
Backtab	<SFT><TAB>
Down Arrow	<Down Arrow>
Right Arrow	<Right Arrow>
Soft Terminal Reset	NA
Select	<CTRL><4>
Remove	NA
Next Screen	NA
F11	NA
F12	NA
F13	NA
F14	NA
F15/Help	NA
F16/Do	NA
F17	NA
F18	NA
F19	NA
F20	NA

Honeywell 6500 52-Key Keyboard Map

HP Emulation Keys

HP Key	Key Sequence
Return	NA
Backspace	<BKSP>
Tab	<TAB>
Up Arrow	<Up Arrow>
Left Arrow	<Left Arrow>
Insert Line	NA
Insert Char	NA
Hard Terminal Reset	NA
Prev	NA
Clear Line	NA
Insert Char with wrap	NA
Scroll Down	NA
F1	<Red><1>
F2	<Red><2>
F3	<Red><3>
F4	<Red><4>
User Key Menu	NA

HP Key	Key Sequence
Enter	<ENT>
Backspace(Delete)	<BKSP>
Backtab	<SFT><TAB>
Down Arrow	<Down Arrow>
Right Arrow	<Right Arrow>
Delete Line	<CTRL><5>
Delete Char	<CTRL><4>
Soft Terminal Reset	NA
Next	NA
Clear Display	NA
Delete Char with wrap	NA
Scroll Up	NA
F5	<Red><5>
F6	<Red><6>
F7	<Red><7>
F8	<Red><8>
System Modes Menu	NA

Honeywell 6500 52-Key Keyboard Map

5250/3270/VT/HP Character Map

Char	Key Sequence
Space	<SP>
!	<Blue><N>
“	<Blue><H>
#	<Blue><, >
\$	<SFT><4>
%	<SFT><5>
&	<SFT><7>
'	NA
(<Blue><C>
)	<Blue><D>
*	<Blue><. >
+	<Blue><A>
,	<, >
-	<Blue><F>
.	<. >
/	<Blue><L>
0	<0>
1	<1>
2	<2>
3	<3>
4	<4>
5	<5>
6	<6>
7	<7>
8	<8>
9	<9>
:	<Blue><G>
;	<Blue>
<	<SFT><, >
=	<Blue><M>
>	<SFT><. >
?	NA
@	<Blue><K>

Char	Key Sequence
A	<SFT><A>
B	<SFT>
C	<SFT><C>
D	<SFT><D>
E	<SFT><E>
F	<SFT><F>
G	<SFT><G>
H	<SFT><H>
I	<SFT><I>
J	<SFT><J>
K	<SFT><K>
L	<SFT><L>
M	<SFT><M>
N	<SFT><N>
O	<SFT><O>
P	<SFT><P>
Q	<SFT><Q>
R	<SFT><R>
S	<SFT><S>
T	<SFT><T>
U	<SFT><U>
V	<SFT><V>
W	<SFT><W>
X	<SFT><X>
Y	<SFT><Y>
Z	<SFT><Z>
[NA
\	<Blue><Q>
]	NA
^	<SFT><6>
_	NA
`	NA

Char	Key Sequence
a	<A>
b	
c	<C>
d	<D>
e	<E>
f	<F>
g	<G>
h	<H>
i	<I>
j	<J>
k	<K>
l	<L>
m	<M>
n	<N>
o	<O>
p	<P>
q	<Q>
r	<R>
s	<S>
t	<T>
u	<U>
v	<V>
w	<W>
x	<X>
y	<Y>
z	<Z>
{	NA
	NA
}	NA
~	NA

Honeywell 6500 52-Key Keyboard Map

5250/3270/VT/HP Character Map

Char	Key Sequence
^@	<CTRL><Blue><K>
^A	<CTRL><A>
^B	<CTRL>
^C	<CTRL><C>
^D	<CTRL><D>
^E	<CTRL><E>
^F	<CTRL><F>
^G	<CTRL><G>
^H	<CTRL><H>
^I	<CTRL><I>
^J	<CTRL><J>
^K	<CTRL><K>
^L	<CTRL><L>
^M	<CTRL><M>
^N	<CTRL><N>
^O	<CTRL><O>
^P	<CTRL><P>
^Q	<CTRL><Q>
^R	<CTRL><R>
^S	<CTRL><S>
^T	<CTRL><T>
^U	<CTRL><U>
^V	<CTRL><V>
^W	<CTRL><W>
^X	<CTRL><X>
^Y	<CTRL><Y>
^Z	<CTRL><Z>
ESC	<ESC>
^\ ^]	<CTRL><7> <CTRL><6>
^^	NA
^_	NA